

IMPORTANT NOTICE

See other side for details.

HVX Setup Procedure

When installing this HVX Validator follow these steps:

- 1. Apply power to the Validator with all switches in the OFF position.**
- 2. Turn ON switch #6, then lastly switch #1. A two-digit calibration factor should be displayed on the side of the Validator. It will appear as if the number is flashing.**
- 3. Turn OFF switch #1, and for a short time a dash “-“ will be displayed. During this time the Validator is storing the calibration values. When this procedure is complete, the display should return to the flashing decimal point.**
- 4. Turn OFF switch #6 to complete the procedure. Finally, set the switches, as you would have them for normal operation. Switches #7-10 should be set based on which denominations you would like to accept.**
- 5. When testing the Validator, verify that there is a flashing dot on the display. If not, make sure that you have set the switches correctly.**